PVC DOOR/WINDOW

SAFETY INSTRUCTIONS

Make sure to use the recommended tools.

Wear proper protective gear.

Follow fixture, power tools, manufacturers' instructions, and user manuals.

Use common sense and follow good construction practices.

TOOL & MATERIAL CHECKLIST

□ miter saw □ 100% acrylic paint
□ cordless drill □ acrylic caulk & gun
□ table saw □ tape measure
□ screws □ utility knife
□ PVC cement □ safety glasses
□ carbide-tipped blade
□ pocket hole jig
□ paint brush

SPECIAL INSTRUCTIONS & NOTES

- · You can use standard woodworking tools, but use carbide-tipped cutting tools and blades.
- Preassemble trim pieces together, installing as one unit rather than one piece at a time.
- · Hot-dipped galvanized or stainless steel nails/screws are best for PVC trim.
- PVC expands and contracts with temperature. If you are installing above 80 degrees F, cut pieces to fight tightly. 60-80 degrees, leave a 1/16-in gap for 18 ft of length. Below 60 degrees, leave a 1/8-in gap. After installation cover gap with acrylic caulk.
- · Fill fastener holes in PVC with acrylic caulk.
- · Glue joints and miters together with PVC cement.
- · Use 100% acrylic paint before in stalling, finish with final coat to cover chalked holes.

STEP BY STEP INSTRUCTIONS

Mitering Corners

 Miter your mouldings to join pieces at corners. An end miter is a 45° cut in the ends of two adjoining pieces of moulding so they fit tightly together.

Moulding Installation

- 1. Use a pocket hole jig to pre-drill holes at joints.
- Cement edges, clamp pieces together, then draw together tightly with pocket screws.
- 3. Apply a continuous 1/2" bead of construction adhesive along the back of moulding lengths.
- 3. Press moulding around window or door frame.
- 4. Secure moulding into place with screws.
- Apply chalk/filler in remaining gaps and smooth with finger.
- 6. Touch-up moulding as needed with 100% acrylic paint.

EXAMPLE INSTALLATION DIAGRAMS

