Assembly Instructions




If you have any questions, please follow these steps ("Find Your Orders" - "Problem with the Order" - "Contact Seller") to contact our customer service. Thanks!

NOTE: There are two packages A and B for thisitem. Please wait patiently if you only receive one for now $\begin{array}{c} \text{NOTE: } \\ \text$

General Assembly Guidelines

- I. Ensure that all parts and hardware are available before beginning assembly.
- ||. Follow each step carefully to ensure the proper assembly of this product.
- III. Two people are recommended for ease in the assembly of this product.
- V. The three main types of hardware used to assemble this product are : wood dowels , screws and bolts.
- V. The provided glue is to secure wood dowels in place. When first inserting dowels, locate the appropriate hole for the dowel, place a small amount of glue in the hole and insert the dowel. Wipe away excess glue immediately.




In future assembly steps when dowels are necessary to attach assembly parts together, place a small amount of glue on the end of the dowel before attaching parts together. Wipe away excess glue immediately.




VI. A Phillips head screwdriver is required for the assembly of this product.




MI. Power tools should not be used to assemble this product.




Mil. Concealed hinges are three-way adjustable.



Horizontal by screw adjustment




In-and-Out
by loosening the hinge-arm
mounting screw or via cam
adjustment




Vertical
Via slots in the mounting
plate or via cam adjustment

Parts List



Hardware List

Α		Ø8x30mm	Wooden dowel	46	pcs
В		Ø10x40mm	Wooden dowel	8	pcs
С		Ø6x35mm	Cam lock	79	pcs
D	\mathfrak{G}	Ø15x11mm	Cam lock	64	pcs
E		Ø15x9mm	Cam lock	15	pcs
F	\bigcirc	Ø30mm	Sticker	79	pcs
G		Ø6x50mm	Bolt	6	pcs
Н		M 4	Hex Key	1	рс
1		M6*12mm	Screw	8	pcs
J		M6*40mm	Screw	12	pcs
K		M 5	Hex Key	1	рс
L		M8*80mm	Screw	4	pcs
M		Ø5/16in	Nuts	8	pcs
N		Ø5/16in	Half-moon part	8	pcs
0	5/	Ø5/16in	Wrench	1	рс
Р		Ø8x70mm	Screw	4	pcs




The hardware quantities listed above are required for proper assembly.

Some extra hardware may also have been included.


Hardware List


Q			Angle iron	2	pcs
R	<	Ø5x12mm		4	pcs
S		Individually packed	Drawer sildes	3	set
Т	⊕	Ø3x12mm	Screw	36	pcs
U	ॐ		Hold hands	3	pcs
V	annand?)	Ø4x9mm	Screw	6	pcs
W			Single head set	20	pcs
X			Double head set	10	pcs
Υ	<i>⊗</i>	Ø4x32mm	Screw	15	pcs
Z			Small White Glue	2	pcs





The hardware quantities listed above are required for proper assembly.


Some extra hardware may also have been included.



















































NOTE:


Refer to the images to identify S-CL8 (left) and S-CR8 (right). Attach S-CL8 to #19 panel and S-CR8 to #19 panel. [T] screws must go in the exact




X2 X12


Step 18 19 G 17 Н G X1 X4









Step 22 Р X4










NOTE:

Refer to the images to identify S-CL8 (left) Attach S-CL8 to #15 panel . [T] screws must go in the exact spots shown.




S	Т	
X1	X3	




NOTE:

Refer to the images to identify S-CR8 (right). Attach S-CR8 to #16 panel. [T] screws must go in the exact spots shown.





S	Т	
	<®	
X1	Х3	





Step 28 ªH 22 🕸 22 21

Н	I
	(4)
X1	X4














Н	J
X1	X12

























E & X5









E & X5













NOTE:

Refer to the images to identify S-DL8 (left) and S-DR8 (right). Attach S-DL8 to #27 panel and S-DR8 to #28 panel. [T] screws must go in the exact spots shown.




Т	S
<	
X18	Х3



F	U	V
0	& &	(Bumming)
X5	X1	X2

Step 43 **F** 0 **F** 0

F	U	V
0	& &	(E)
X5	X1	X2



F	U	V
0	& &	(3)
X5	X1	X2

