

Assembly Instructions





Overbed Table


Assembly Instructions:

- 1. Carefully read these instructions and keep them for future reference.
- 2. Refer to the parts list for guidance and ensure that you have all the pieces before starting the assembly process, if anything is missing, damaged, incorrect, contact us FIRSTLY BEFORE assembling.
- 3. When assembling, place all parts on a soft, clean, and flat surface, such as a carpet, to prevent any scratches.
- 4. To avoid misalignment of the holes, Please don't full tighten the screws until you ensure all parts in place.










(!\Caution)

Make sure all parts are included. Most board parts are labeled or stamped on the raw edge. Contact us for free replacement if having damaged or missing parts.

Parts & Hardware List




Hardware List


Α	X6+1	В	X6+1	С	X8+1	D	X14+1	Е	X11+1	F	X1
						Divita		D			
φ6X35mm		φ15X12mm		φ8X30mm		φ3.5X14mm		φ7X47mm		M4X55mm	
G	X1	Н	X10+1	I	X16+1	J	X1	K	X1	L	X4
J.		@		①						Ą	
			(12mm	M6X	(50mm	58X	35mm	123X7	2X7mm		
		M	X4	N	X1	0	X2	Р	X1		
			50mm	L300	mm	L300)mm				

Installation of Cams and Pins


Screw the pin into the hole. To set the cams correctly, ensure that the arrow on the cam is opening to the hole of the pin it is locking. Lock the cam by turning the cam head with a screwdriver until it is tightened. Please do not use an electric screwdriver to assemble the unit.




Read each step carefully before starting. It is very important that each step of instruction is performed in the correct order. If these steps are not followed in sequence, assembly difficulties will occur.












2

Α	X6				
φ6X35mm					




D	D X4		X2	
On				
φ3.5>	(14mm	L300mm		






(5)





В	X6	С	X4	
Ø15X	12mm	Ø8X3	30mm	

6




Á	X4						
@							
M6X12mm							
















Н	X2	J	X1	K	X1
@			P		\geqslant
M6X12mm		58X35mm		123X72	X7mm



