



Assembly Instructions

Hans Wegner Shell Chair

Label	Picture	Qty	Step 1	Step 2	Step 3
A		1			
B		1			
C		1			
D		1			
E		1			
F		1			
G		1			
H1	M6*22mm	12			
H2	M6*22mm	17			
H3		2			
H4	M6*22mm	10			
H5	M6*18mm	3	Pls adjust the tightness of screws appropriately before the last screw has been settled.		