




















Assembly Instruction






 Hammer and Screwdriver
 are not included !!




NO.	QTY.	LINEDRAWING
(A)	4	
(B)	8	
(C)	16	
(D)	16	
(E)	12	 8x40
(F)	1	
(G)	4	 3.5x35
(H)	36	 3.5x14
(I)	6	 3.5x12
(J)		
(K)	16	
(L)	24	 $\phi 20$
(M)	4	 M6x30
(N)	2	
(O)	1	



PARTS LIST




NO.	QTY.
①	1
②	1
③	1
④	1
⑤	1
⑥	1
⑦	1
⑧	1
⑨	1
⑩	1
⑪	1
⑫	1
⑬	1
⑭	1
⑮	1
⑯	2




1




F		H	
	1x		4x




2




E		8x40	4x
C		4x	
D		4x	

3





E		8x40	8x
C		8x	
D		8x	



4




5





6




7




8



9



10



C




4x

D



4x

11



F




1x

H



4x

12



A



4x

H




8x

I



4x


J



2x

5 OF 6

13





H



16x

14




J



1x

L



24x

N



2x

I



2x

