




Assembly Instruction




Hammer and Screwdriver
are not included !!




NO.	QTY.	LINEDRAWING
(A)	26	
(B)	26	
(C)	12	
(D)	2	
(E)	8	
(F)	2	
(G)	24	
(H)	2	
(I)	4	
(J)	26	
(K)	10	

PARTS LIST




NO.	QTY.
①	1
②	1
③	1
④	1
⑤	1
⑥	1
⑦	1
⑧	1
⑨	1
⑩	2
⑪	2
⑫	2
⑬	2
⑭	2

1




	
H	G
2x	8x


2




	
A	B
1x	1x
	
C	J
2x	1x


3




	
A	
2x	
	
B	J
2x	2x

4




	
A	
2x	
	
B	J
2x	2x

5




A	B
	
8x	8x
C	J
	
4x	8x

6





7



A	B
	
5x	5x
C	J
	
6x	5x


8



K

10x

9




I



4x

10



X2


E



Ø3.5x35


8x

11



X2

12



X2

A



8x

B




8x

J




8x

13





H	G
2x	8x

15



14



Tight the Third screw after
drawer adjusted in a Suitable
location.

F	G
2x	8x

D
2x