















L 4\*50 M 8\*40  
2PCS 2PCS

K 300mm  
K<sub>1</sub>\*2 K<sub>2</sub>\*2  
2PCS

A	B	C 8*40	D 3.5*14	E 3.5*35	F	G 4*18	H	I	J
25PCS	25PCS	4PCS	24PCS	4PCS	2PCS	4PCS	2PCS	4PCS	4PCS


1  452*405 1PCS	2  390*390 1PCS	3  885*390 1PCS	4  885*390 1PCS	5  390*370 1PCS
6  452*100 1PCS	7  385*53 1PCS	8  365*300 1PCS	9  385*125 1PCS	10  300*100 1PCS
11  300*100 1PCS	12  335*100 1PCS	13  345*294 1PCS	14  582*350 3PCS	15  387*350 7PCS
16  879*400 1PCS				




## Hardware installation demonstration

NOTE:Please make sure "A"hardware tightened and can't be pulled out!


I



II



III




IV



Scan QR code for assembly video

①




①

C


③

④



A

A



A

A

A

A

A

A

A

A

A

A

A

A

A

A

A

A

A

A

A

A







A\*12



C\*2

put A on board ① ③ ④  
put C on board ③ ④

②




put A on board ⑥

put C on board ②

	A*6
	C*2

③



Make sure the arrow on the screw align to the hole on the side.


put B on board ② ⑤



B\*4

④


put B on board ② ⑤



B\*4


5

put B on board ② ③ ④




B\*10

⑥




	D*8
	K <sub>1</sub> *4

7



	A*7
	F*2
	G*4

⑧




put B on board ⑧


	B*3
	D*4
	K <sub>2</sub> *2

9


put B on board ⑩ ⑪




⑩




11



12




13






	D*4
	H*2
	I*4
	J*4


14




	L*2
	M*2



Please install tip-proof fitting.



END



D\*4