





IMPORTANT: DON' T FASTEN BOLTS UNTIL ALL PARTS IN POSITION.


PART

A




x1

B




x1

C




x1

D




x2

E




x1

F



x2

G



x1

1



M6x30  
X6

4



X1

2



M6X12  
X5

5




M8  
X6

3




M6x40  
X10

1



③ X10

2




② X5

④ X1

⑤ X6

3

⑥



① X6