


















Assembly Instruction




NO.	QTY.	LINEDRAWING
(A)	44	
(B)	44	
(C)	36	 Ø8x40
(D)	1	
(E)	1	
(F)	4	 M6x15
(G)	4	
(H)	10	
(I)	2	 3.5x35 3.5x14
(J)	4	 M6x20
(K)	44	
(L)	1	
(M)	1	
(N)	1	



 Hammer and Screwdriver
 are not included !!




PARTS LIST




NO.	QTY.
①	1
②	1
③	1
④	1
⑤	1
⑥	1
⑦	1
⑧	1
⑨	1
⑩	1
⑪	1
⑫	1
⑬	3

1




A	B	C
2x	2x	2x

2




A	B	C	H
6x	6x	4x	6x

3




A	B	C
6x	6x	4x

4




A	B	C
2x	2x	2x

5




A	B	C
6x	6x	4x

6




A	B	C
6x	6x	4x

7




A	B	C
6x	6x	6x

8




C	A	B
6x	6x	6x




N 1x	M 1x
E 1x	J 4x

10




F 4x	C 4x	H 4x
A 4x	B 6x	

11



G 4x	D 1x
---------	---------

12



I 2x	K 44x
---------	----------