







PARTS LIST



HARDWARE LIST


NO.	Drawing	Description	Qty	PCS SET	NO.	Drawing	Description	Qty	PCS SET
A		ø15x12	16	PCS	CL1		10"	1	SET
B		ø7x35	16	PCS	CR1				
C		ø8x30	16	PCS	DL1				
D		ø3.5x16	14	PCS	DR1				
E		ø4x40	4	PCS					
F		ø3.5x14	2	PCS					
G			1	PCS					
F		ø3.5x14	8	PCS					

1 ATTENTION

During assembly, first loosely align all screws with the corresponding pre-drilled holes and then tighten the screws one by one.


STEP 1

H x4pcs
CL1 x1pcs
CR1 x1pcs




STEP 2

A x4pcs
B x4pcs




STEP 3

- A x2pcs
B x2pcs
C x4pcs



STEP 4

- A x2pcs
B x2pcs
C x4pcs




STEP 5

A x4pcs


B x4pcs

C x8pcs



STEP 6


D x14pcs




STEP 7

A x4pcs

B x4pcs



STEP 8




STEP 9

E x4pcs

F x2pcs

G x1pcs




STEP 10


H x4pcs

DL1 x1pcs

DR1 x1pcs



STEP 11



STEP 12

