











Assembly Instruction




NO.	QTY.	LINEDRAWING
Ⓐ	4	
Ⓑ	4	
Ⓒ	6	 6x60
Ⓓ	4	 7x50
Ⓔ	4	
Ⓕ	1	

 
Hammer and Screwdriver
are not included !!




PARTS LIST






NO.	QTY.
①	1
②	1
③	2


1




2




A	B
	
4x	4x



D

4x


3



4



C	F
	
6x	1x

E

4x