












Assembly Instruction






Hammer and Screwdriver
are not included !!





NO.	QTY.	LINEDRAWING
(A)	34	
(B)	34	
(C)	26	
(D)	16	
(E)	8	 3.5x35
(F)	8	
(G)	24	 ø20
(H)	1	

PARTS LIST



NO.	QTY.
①	1
②	2
③	2
④	2
⑤	2
⑥	2
⑦	2
⑧	2



1



E 3.5x35

4x



2



E 3.5x35

4x

3



C

6x



A



10x



B


10x

4



C

3x



A

4x




B

2x


4x

5




C		3x	2x
A		4x	
B		4x	

6




A		2x	
B		2x	

7



A		2x	
B		2x	

8



C		8x	G		24x
D		16x	F		8x