











PARTS LIST



HARDWARE LIST


NO.	Drawing	Description	Qty	PCS SET	NO.	Drawing	Description	Qty	PCS SET
A		∅15x9	4	PCS	J		4MM	1	PC
B		∅7x35	4	PCS	K		∅3.5x16	18	PCS
C		∅6x30	4	PCS	L		∅5x(10+10)	10	PCS
D		∅3.5x14	2	PCS	M		∅3x12	2	PCS
E			1	SET	N			2	PCS
F		∅4x40	3	PCS	O		∅4x35	2	PCS
G		∅35x190	4	PCS	P			2	PCS
H		∅4x40	6	PCS	Q		180x20x3	2	PCS
I		M6x20	8	PCS	R		∅7.8x38	2	PCS

1 ATTENTION

During assembly, first loosely align all screws with the corresponding pre-drilled holes and then tighten the screws one by one.

STEP 1


B x4pcs



STEP 2


D x2pcs

E₁ x1pc




STEP 3

A x4pcs
C x2pcs



STEP 4


C x2pcs
F x3pcs
H x4pcs



3


STEP 5

G x4pcs
I x8pcs
J x1pc




STEP 6

K x16pcs



STEP 7

L x8pcs




STEP 8

E₂ x2pcs

M x2pcs


N x2pcs

O x2pcs




STEP 9

L x2pcs
P x2pcs



STEP 10


K x2pcs
Q x2pcs



6

STEP 11

H x2pcs
R x2pcs



STEP 12

