



-



Assembly Instructions






Computer Table




X2



When using the electric screwdriver ,
Reduce the power and torque to avoid damaging the furniture








Caution

Make sure all parts are included. Most board parts are labeled or stamped on the raw edge. Contact us for free replacement if having damaged or missing parts.

Parts & Hardware List





Hardware List

A	X64+1	B	X64+1	C	X34+1	D	X20+1	E	X10	F	X10+1	G	X2	H	X8+1
															
Ø6X40mm		Ø15X12mm		Ø8X30mm		4X25mm		17x16x10.5		3X18mm		M6XØ23mm		M6X12mm	


I	X1	J	X2
			
M4X55mm		Ø20X2.2mm	

Installation of Cams and Pins



Screw the pin into the hole. To set the cams correctly, ensure that the arrow on the cam is opening to the hole of the pin it is locking. Lock the cam by turning the cam head with a screwdriver until it is tightened. Please do not use an electric screwdriver to assemble the unit.




Read each step carefully before starting. It is very important that each step of instruction is performed in the correct order. If these steps are not followed in sequence, assembly difficulties will occur.





1





A	X12
	
Ø6X40mm	

2




B	X6	C	X4
			
Ø15X12mm		Ø8X30mm	

3





B	X2	C	X4
			
Ø15X12mm		Ø8X30mm	

4






5






B	X4	C	X4
			
Ø15X12mm		Ø8X30mm	

6





D	X12
	
4X25mm	

7




A	X24
Ø6X40mm	

8




B	X12
Ø15X12mm	

9




B	X12
Ø15X12mm	

10




11




C	X2
	
Ø8X30mm	

12




C	X2
	
Ø8X30mm	

13







C	X2
	
Ø8X30mm	

14





15




A	X12
	
Ø6X40mm	

16




B	X6	C	X6
			
Ø15X12mm		Ø8X30mm	

17






18




B	X6	C	X6
			
Ø15X12mm		Ø8X30mm	

19



D	X8
	
4X25mm	



20





X2

G	X2
	
M6XØ23mm	


21



22





screw down





H	X8	I	X1	J	X2
					
M6X12mm		M4X55mm		Ø20X2.2mm	

23





24






E	X10	F	X10
			
17x16x10.5		3X18mm	

25





X2





A	X16
	
Ø6X40mm	

26





B	X8
	
Ø15X12mm	

27




28





B	X8
Ø15X12mm	

29



30



C	X4
	
Ø8X30mm	

