




ASSEMBLY INSTRUCTION






(A)	x 16	(B)	x 26	(C)	x 19	(D)	x 6	(E)	x 8	(F)	x 16
	M6x40		M6x30		M6x12				M7x50		M7x40
(G)	x 2	(H)	x 8	(I)	x 1	(J)	x 1	(K)	x 3	(L)	x 4
			M6x15		M4				M6		
(M)	x 4	(N)	x 2	(O)	x 2	(P)	x 1	(Q)	x 1	(R)	x 4
			4x30		M4x14						

① x1PC



② x1PC




③ x1PC



④ x1PC



⑤ x1PC




⑥ x1PC



⑦ x2PCS




⑧ x2PCS




⑨ x1PC



⑩ x2PCS




⑪ x2PCS




⑫ x2PCS




⑬ x2PCS




⑭ x2PCS



⑮ x2PCS



⑯ x4PCS




⑰ x4PCS




⑱ x2PCS




⑲ x1PC



⑳ x1PC




1



x2


(H)	x 8
	M6x15

2



(A)	x 8	(I)	x 1
M6x40		M4	


3



(A)	x 4	(I)	x 1

M6x40 M4


4



(C)	x 4	(G)	x 2	(I)	x 1

M6x12 M4


5



(B)	x 12	(I)	x 1

M6x30 M4


6



(B)	x 8	(I)	x 1

M6x30 M4


7



(C)	x 10	(I)	x 1	(J)	x 1	(K)	x 2

M6x12 M4 M10 M6


8



(C)	x 5	(I)	x 1	(J)	x 1	(K)	x 1

M6x12 M4 M10 M6


9



(B)	x 4	(I)	x 1


M6x30 M4

10




(D)	x 4

11




(L)	x 4	(I)	x 1
			M4


12



(M)	x 4	(I)	x 1
			M4




13



(F)	x 4	(I)	x 1


M7x40 M4

14



(D)	x 2


15



(F)	x 8	(I)	x 1

M7x40 M4


16



(E)	x 8	(I)	x 1

M7x50 M4


17



(B)	x 2	(I)	x 1

M6x30 M4


18



(A)	x 4	(I)	x 1

M6x40 M4

19



(O)	x 2
-----	-----



M4x14


(I)	x 1	(P)	x 1
-----	-----	-----	-----



M4



20



(F)	x 4	(I)	x 1
-----	-----	-----	-----




M7x40




M4

21




22




(R)	x 4
	

23



24

Please prepare the tools



(N)	x 2
	4x30