


PARTS LIST

Item *	Description	Qty	Part No.
A	LEG FRAME ASSEMBLY	2	35-240
B	TOP RAIL	2	35-260
C	TOP RAIL CLEAT - CENTER	4	35-261
D	TOP RAIL CLEAT - OUTER	2	35-262
E	TOP RAIL SUPPORT	2	35-245
F	CORNER SUPPORT - LEFT HAND	2	35-263
©	CORNER SUPPORT - RIGHT HAND	2	35-264
AB	WOOD SCREW - 1-1/2" - (STEP *4)	8	991707
AC	MACHINE BOLT - 2-3/8" - (STEP *3)	4	991733
AD	WOOD SCREW - 2" - (STEPS *1 & *2)	16	991719
(AE)	"T" NUT - INSTALLED AT FACTORY	4	991711










STEP #1 Attach Top Rail Support (E) to Top Rail (B)

- (1) Position a Top Rail (B) as shown Finished side down Staple side up!
- 2 Attach the Top Rail Supports (E) to the Top Rail (B) using 2 2" wood screws (AD).
- (3) Attach the other Top Rail (B) in the same manner.

 Be sure that the Top Rail Support is square to the Top Rail before tightening the screws.




STEP #2 Attach Cleats (C & D) to Top Rail Assembly

- 1) Position the Top Rail Assembly from Step *1 as shown.
- 2 Attach the 4 Center Cleats (C) and 2 Outer Cleats (D) using 12 2" wood screws (AD).


 Pilot holes have been provided in the Top Rails and grooves in the Cleats to locate the parts.

 Be sure that you position the Outer Cleats (D) as shown



STEP #3 Attach Upper Assembly to Leg Frames (A)

- 1) Position the Upper Assembly and Leg Frames Assemblies (A) as shown.
- Secure the Upper Assembly to the Leg Frames using 4 Machine Bolts (AC).
 "T" Nuts have been installed at the factory for easier assembly



NOTE: BE SURE THAT THE LATTICE IS POSITIONED AS SHOWN

STEP *4 Attach the LH (F) & RH (G) Corner Supports

- 1) Attach the LH Corner Support (F) using 2 wood screws (AB). Be sure that the support is tight against the Top Rail and Leg.
- (2) Attach the other Corner Supports in the same manner.

