





Assembly Instructions



Your satisfaction is our top priority. If you encounter any issues with this product, such as missing or damaged parts, we're here to help. Please retain the original packaging and take photos of the packaging and the product, then contact us as soon as possible.


Warm Tips


1. Carefully read these instructions and keep them for future reference.
2. Check the parts list and confirm everything's there before starting assembly.
3. When assembling, put all parts on a soft, smooth surface like a carpet to avoid scratches.
4. Don't fully tighten screws until all parts are confirmed in place to avoid misalignment.



We recommend using hand tools for assembly.

If an electric screwdriver is used, reduce power and torque to avoid damage to the product.







⚠ Caution

Make sure all parts are included. Most board parts are labeled or stamped on the raw edge. Contact us for a free replacement if you encounter any damaged or missing parts.


Parts List




① 1pc




② 2 pcs




③ 2 pcs




④ 4 pcs



⑤ 2 pcs








⑥ 2 pcs





⑦ 2 pcs



Hardware List

A	X16+1	B	X16+1	C	X8+1	D	X4	E	X1
									
M6X30 mm		M6X50 mm		M6X70 mm		M8XØ35 mm		M4X55 mm	

1



screw down 




A	X16	E	X1
			
M6X30 mm		M4X55 mm	

2



screw down 




B	X4
	
M6X50 mm	

3



screw down 




C	X8
	
M6X70 mm	



4


screw down 




B	X12
	
M6X50 mm	

5

screw down 




D	X4
	
M8XØ35 mm	

6



