








① x1




② x2




③ x1




④ x1




⑤ x1




⑥ x1




⑦ x1




⑧ x1




⑨ x1




⑩ x1




⑪ x1




⑫ x1



⑬ x1



Ax26



Bx26



15\*9.5mm

Cx16




φ8\*30

Dx2




Ex4



4\*20mm

Fx4



Gx6



3.5\*12mm

Hx4




3\*14mm

Ix2




3.5\*50mm


Jx2



Kx1



Lx4




Mx20



4\*14mm


# STEP 1

-  Ax8
-  Cx6



# STEP 2


-  Ax4
-  Cx4
-  Bx4



# STEP 3




Bx4



# STEP 4




Bx4



# STEP 5


 Ax6



# STEP 6

 Ax4


 Bx4




# STEP 7



Bx6




# STEP 8





# STEP 9

-  Ax4
-  Cx6
-  Ix2




# STEP 10


-  Hx4
-  Jx2




# STEP 11




# STEP 12




# STEP 13




# STEP 14



# STEP 15



Lx4



# FNISHI

