



# Assembly Instruction
















# COMPONENTS

Part Nr.	Qty	Part Nr.	Qty	Part Nr.	Qty
A	1pcs	F	2pcs	L	1pcs
B	1pcs	G	1pcs	M	1pcs
C	1pcs	H	2pcs	N	2pcs
D	1pcs	J	1pcs		
E	2pcs	K	1pcs		




# HARDWARE LIST

<p>① x 10</p>  <p>M6x30mm</p>	<p>② x 9</p>  <p>M6x12mm</p>	<p>③ x 24</p>  <p>D5x50mm</p>	<p>④ x 12</p>  <p>6x15</p>
<p>⑤ x 6</p>  <p></p>	<p>⑥ x 1</p>  <p>M6</p>	<p>⑦ x 2</p>  <p>D3.5x15mm</p>	<p>⑧ x 2</p>  <p></p>
<p>⑨ x 6</p>  <p></p>	<p>a x 1</p>  <p></p>	<p>b x 1</p>  <p>#4</p>	<p>c x 1</p>  <p>#3</p>
<p>d x 1</p>  <p></p>			


1

M6x12mm


6x15



2 x 4





4 x 4




here is a end stop



Noted the direction of (J) and (K)





Noted the holes of X support at part (C) are here .



2




3




4


M6x30mm



① x 6




⑤ x 6




5

M6x12mm


6x15




② x 5



④ x 4




⑥ x 1




6

D5x50mm




3 x 8




7

M6x30mm




1 x 4

6x15




4 x 4



8

D3.5x15mm




7 x 2



8 x 2



9 x 6



a x 1

