












PARTS LIST



HARDWARE LIST


NO.	Drawing	Description	Qty	PCS / SET	NO.	Drawing	Description	Qty	PCS / SET
A		⌀15x9	12	PCS	K		M6x25	8	PCS
B		⌀7x35	12	PCS	L			12	PCS
C		⌀6x30	8	PCS	M		M4x20	4	SET
D		⌀3.5x14	2	PCS	N		108x25x9MM	2	PCS
E			1	SET	O		⌀3x12	2	PCS
F		⌀4x40	3	PCS	P			2	PCS
G		⌀4x40	6	PCS	Q			2	PCS
H		⌀3.5x16	18	PCS	R		180x20x3	2	PCS
I		4MM	1	PCS	S		⌀7.8x38	2	PCS
J		M6x30	4	PCS					

1 ATTENTION

During assembly, first loosely align all screws with the corresponding pre-drilled holes and then tighten the screws one by one.


STEP 1

B x12pcs



STEP 2


A x2pcs
C x2pcs
D x2pcs
E1 x1pc



2


STEP 3

A x5pcs
C x2pcs




STEP 4

A x5pcs
C x2pcs




3



4


STEP 7

I x1pcs
J x4pcs



STEP 8


K x8pcs



5


STEP 9

L x12pcs



STEP 10


E2x2pcs
M x4pcs
N x2pcs
O x2pcs



6


STEP 11

P x2pcs
Q x2pcs



STEP 12


H x2pcs
R x2pcs



7

STEP 13

G x2pcs
S x2pcs



STEP 14

