
Installation Diagram

NAME	Coat Rack

Note:(installed)inthepartslistand hardwarelistItmeansithasbeeninstalled Inthefinishedproductandisnotincluded Inthehardwarepackage!!



Parts List


NO.	NAME	icon	Specification	amount
1	B asket side frame		345*395*20mm	2
2	Basck front and back frames		345*355*40mm	2
3	Basket bottom plate		355*355*17mm	1
4	Thickened Lower Lathe-Turned		280*ø55mm	1
5	Upper Middle Post		395*ø40mm	1
6	Upper Middle Post1		395*ø40mm	1
7	Upper Middle Post2		395*ø40mm	1
8	TopLathe-TumedSection		345*200*60mm	1
9	Long Hook Arm		125*ø26mm	5
10	Medium-Long Hook Arm		75*ø26mm	2
11	Short Hook Arm		45*ø26mm	2

Hardware Accessories List

NO.	NAME	icon	Specification	amount
A	Hexagon socket screw		M8*35mm	3
B	Flat W asher		M8*19mm	3
C	Hex Key with Phillips Tip		M5*65mm	1
D	Thre aded Stem C aster		M6x10mm Caster 25mm Wheel Height 38mm with Brake	2
E	Thre aded Stem C aster		M6x10mm casters, 25mm wheel, height 38mm, without brake	2
F	Open-End Wrench		10mm Wrench (Open-End)	1
G	Hex Socket Connector Bolt		M7*30mm	4
H	Allen Wrench		M4*100mm	1
I	Flat Head Hex Screw		M6*30mm	9
J	Assem y Rod		L=40MM	9
K	Lo cking C ollar		ø15MM	9
L	Dowel Pin		ø 8*30MM	13
M	Huanmei Brand Adhesive Tape		ø 20MM	9
N	Animal Eye		ø 20mm	3
O	3M Adhesive		ø 15*1MM	3

pecification Name:Coat Rack


Step1



After unpacking, please check all parts against the instruction manual to ensure the quantities are correct before beginning assembly.


▸As shown, attach Part 1 using hardware J.

Step2




▸As shown, connect Parts 2 and 3 using hardware K and L
Then cover hardware K with hardware O.

Step3




▸As shown, assemble Part 1 with the
Step 2 assembly using hardware I and L.

Step4



▸As shown, attach Part 1 to the assembly from Step 3
using hardware I and L.

Step5



▸As shown, assemble using hardware K,
then cover hardware K with hardware O.。

Step6




Image 1

mage 2

▸Image 1.

Attach hardware D and E to the bottom

holes of the Step 5 assembly using hardware F


▸Image 2

Align Part 4 with the two center holes on the bottom.

Use hardware C to fasten hardware A and B.


pecification Name:Coat Rack

Step7




▸As shown, fasten Part 5 to the assembly from Step 6

Step8




As shown, install hardware G onto Part 6 and the Step 7 assembly using hardware H

Step9




▸As shown, install hardware G onto Part 7 and the Step 8 assembly using hardware H

Step10




▸As shown, install hardware G onto Part 8 and the Step 9 assembly using hardware H

Step11



▸As shown, fasten Parts 9, 10, and 11 to the assembly fr om Step 10.

Step12



First, attach hardware O to the back of hardware M. Then stick the assembled part to both sides of Part 8 as shown.

▸As shown, assembly complete