
ASSEMBLY INSTRUCTIONS

COUNTER HEIGHT BAR TABLE



Phillips Screwdriver (Not provided)





A

Spring Washer
8 PCS




B

Flat Washer
8 PCS




C

Hinge
8 PCS




D

M6*40
6 PCS




E

M8*70
8 PCS



F


M4*50
4 PCS




G

1 PC


1




2




3




4




5




6




7




8




9




10





11



01










DO NOT TIGHTEN BOLT COMPLETELY.

02









DO NOT TIGHTEN BOLT COMPLETELY.


03






TIGHTEN BOLT COMPLETELY.

04






DO NOT TIGHTEN BOLT COMPLETELY.

05

F



4 PCS




TIGHTEN BOLT COMPLETELY.


06

C



8 PCS





BE SURE TO CHECK ALL BOLTS ARE SECURELY TIGHTENED PRIOR USING THIS TABLE.