


ASSEMBLY INSTRUCTIONS


ITEM NO.:N707P392140






















IMPORTANT NOTE:

- ① PLACE ALL PARTS ON A CLEAN AND SMOOTH SURFACE SUCH AS A RUG OR CARPET TO AVOID THE PARTS FROM BEING SCRATCHED.
- ② BEFORE YOU BEGIN, KINDLY FOLLOW THE ASSEMBLY INSTRUCTIONS STEP BY STEP.
- ③ DO NOT TIGHTEN ALL SCREWS AND BOLTS UNTIL THIS ITEM IS FULLY SET-UP.

Detail View



N707P392140

1		2		3		4	
1x		1x		1x		1x	
5		6		7		8	
1x		1x		1x		1x	
9		10		11		12	
1x		1x		1x		1x	
13		14		15		16	
1x		1x		1x		1x	
17		18		19		20	
1x		1x		1x		1x	
21		22		23		24	
1x		1x		1x		2x	
25		26		27		28	
2x		1x		1x		1x	
29		30		31		32	
1x		1x		2x		1x	

33



1x

34



1x

35



2x

36



2x

37



1x

38



1x

39



2x

40



2x

41




2x

42



1x

43



1x

44



2x

45



2x

Hardware List

A	 Ø 3.5*60 16x	B	 Ø 3.5*40 26x	C	 Ø 3.5*35 2x	D	 Ø 3.0*30 10x
E	 Ø 3.0*28 34x	F	 Ø 3.0*18 6x	G	 Ø 3.0*16 20x	H	 Ø 3.0*10 2x
I	 Ø 6.0*20 24x	J	 Ø 6.0*60 9x	K	 Ø 6.0*55 5x	L	 Ø 6.0*45 6x
M	 Ø 6.0*35 2x	N	 Ø 6.0*16 2x	O	 2x	P	 16x
Q	 14x	R	 2x	S	 3x	T	 2x
U	 2x	V	 2x	W	 4x	X	 2x
Y	 4x	Z	 1x	AA	 1x		



ASSEMBLY TOOLS REQUIRED(NOT INCLUDED)





PLEASE BE CAREFUL DO NOT DAMAGE THE HOLE
POSITION WHEN YOU USE POWERTOOLS !


P*16



1

P*16

D*4
J*4
L*2



3.0*30MM

D*4

6.0*60MM
J*4

6.0*45MM
L*2


AA*1

2



3

A*6

Front





3.5*60MM
A*6




X2

B*18
I*24
X*2
Y*4
V*1




4

V*1	3.5*40MM	6.0*20MM	X*2	Y*4




5



6

3.5*60MM	3.5*35MM
A*2	C*2
6.0*60MM	6.0*55MM
J*5	K*5
	AA*1


M*2



7



6.0*35MM
M*2

E*12



8

3.0*28MM
E*12





9

3.5*60MM
A*4

6.0*16MM
N*2

A*4



10

3.5*60MM
A*4

F*6
G*4
R*2
S*2
V*1

28

F

R

12

O

G

S

S*2	V*1
3.0*18MM	3.0*16MM
F*6	R*2

11

B*8
G*2
S*1

25

B

10

G

S

3.5*40MM	3.0*16MM	S*1
B*8	G*2	

12

AA

L*4

L

10

6.0*45MM

L*4

AA*1

13

O*2




O

14

O*2

14

Q*14




15



Q*14

16

E*8




17

3.0*28MM

E*8

18


D*6



3.0*30MM

D*6

G*6




19

3.0*16MM

G*6

G*8
U*2




20

3.0*16MM

G*8

U*2

E*6
H*2
T*2



21

3.0*28MM

E*6


3.0*10MM

H*2



T*2

E*8




22

3.0*28MM


E*8

W*4
Z*1



23

~	
W*4	Z*1



24