
VESTIL MANUFACTURING CORP.
2999 N. Wayne St., Angola, IN 46703
Ph: 260-665-7586 · Fax: 260-665-1339
E-mail: sales@vestil.com · Website: www.vestil.com

CAN-A INSTRUCTIONS



Instructions:

1. Place 5 gallon bucket into cradle.
2. Place locking arm on top of bucket and tighten thumb screw. This is done so that when the bucket is tipped, the arm prevents the bucket from falling out.
3. Release locking arm and remove bucket