
















ASSEMBLY INSTRUCTION








TIPS

1. Please read the instructions fully before assembly. These instructions include important information which could ensure correct assembly. We have been working on providing high quality products for you. However, in the rare instance that your product is defective, missing parts or there are some issues, please don't hesitate to contact our customer service to submit parts requirements, assembly suggestion, or warranty claims, and we will give the best solution as soon as possible. If necessary, we need you to provide some more clear pictures of the issue.
2. Insert the screws in holes and tighten the screws, but not too tight, 70%~80% is ok, finally tighten all the screws. If some issues happened that some screws can not target to the hole or some parts are difficult to install, please adjust the tightness of the screws.
3. 2 people are recommended to finish



1  Right rear of bedside X2	2  Left rear of bedside X2	3  Head board leg X2	4  BOW X1
5  on both sides of the bedside X2	6  Bedtail X1	7  Bedside edge strip X1	8  Skeleton arrangement X14
11  Bed support 1 X1	12  Bed support 2 X1	13  Bed support 3 X4	14  Midfoot X1
15  Centre Support Leg X2	16  four Hole Corner Code X2	17  Metal Corner Bracket X2	20  Support Foot X2
22  Hardware Middle Leg X2	22  Connecting Iron Sheets X2		

Hardware List

A  Bolts(M8x45mm) × 25	B  Bolts(M8x16 mm) × 42	C  M8 Flat Washer × 67	D  Allen Key × 1
F  Bolts(M8x40mm) × 2	G  Op end-ended Spanner × 1	H  Bolts(M6x16 mm) X8	I  M6 Flat Washer × 8
J  Bolts(M6x40mm) × 8	K  M6 × 1	L  M6 × 1	



Step1:

A  x8

B  x8


C  x16

D  x1





Step2:

- (A)  x8
- (B)  x8
- (C)  x16
- (D)  x1







Step3:

- (A)  x4
- (B)  x4
- (C)  x8
- (D)  x1




Step4 :

- (B)  x16
- (H)  x8
- (C)  x18
- (D)  x1
- (I)  x8
- (L)  x1
- (J)  x8
- (K)  x1




Step5:

- (B)  x4
- (C)  x4
- (D)  x1




Step6:

- (A)  x4
- (B)  x2
- (C)  x4
- (D)  x1
- (G)  x1




Step7:

- (B)  x6
- (C)  x6
- (D)  x1



Step8

- (A)  x1
- (C)  x1
- (D)  x1



Step12:

