



Installation & Assembly



Tools Recommended

EN_IMPORTANT, RETAIN FOR FUTURE REFERENCE: READ CAREFULLY.

FR_IMPORTANT: A LIRE ATTENTIVEMENT ET À CONSERVER POUR CONSULTATION ULTÉRIEURE.

ES_IMPORTANTE, LEA Y GUARDE PARA FUTURAS REFERENCIAS.


PT_IMPORTANTE, RETER PARA REFERÊNCIA FUTURA: LEIA ATENTAMENTE.

DE_WICHTIG! SORFGFÄLTIG LESEN UND FÜR SPÄTERES NACHSCHLAGEN AUFBEWAHREN.


IT_IMPORTANTE! CONSERVARE IL PRESENTE MANUALE PER FUTURO RIFERIMENTO E LEGGERLO ATTENTAMENTE.

PARTS


A x04




B x03




C x02




D x02




E x01




F x01




G x01




H x01




I x01




J x01



K x01




L x01




HARDWARE


M x14
M4*12
+1(spare)




N x14
M4*35
+1(spare)



O x06
M6*40
+1(spare)



P x04
M6*45



Q x04
M6




R x01
M10




S x04
M6*50




T x01
M4






P x04
M6*45

Q x04
M6




M x06
M4*12




O x03
M6*40

03




S x04
M6*50

04




M x08
M4*12

05




O x04
M6*40

06



N x12
M4*35

07



N x02
M4*35

Done

