


































WCM6006DC

①	1PCS	②	1PCS	③	1PCS	④	1PCS
							
⑤	1PCS	⑥	2PCS	⑦	1PCS	⑧	1PCS
							
⑨	1PCS	⑩	1PCS	⑪	1PCS	⑫	1PCS
							
⑬	1PCS	⑭	1PCS	⑮	2PCS	⑯	2PCS
							
⑰	2PCS	⑱	1PCS	⑲	1PCS	⑳	2PCS
							
㉑	1PCS	㉒	1PCS	㉓	1PCS	㉔	2PCS
							
㉕	1PCS	㉖	1PCS	㉗	1PCS	㉘	1PCS
							


 A M6*50(8PCS)	 B M3.5*60(9PCS)	 C M3.5*50(16PCS)
 D M3.5*40(29PCS)	 E M3.5*30(8PCS)	 F M3.5*25(16PCS)
 G M3.0*18(8PCS)	 H 2PCS	

ASSEMBLY TOOS REQUIRED(NOT INCLUDED)




PLEASE BE CAREFUL DO NOT DAMAGE THE HOLE
POSITION WHEN YOU USE POWERTOOLS

1




C M3.5*50(8PCS)

2




3




(F) M3.5*25(8PCS)

4




(C) M3.5*50(4PCS)

5




(C) M3.5*50(4PCS)


6



7




8




(D) M3.5*40(4PCS)

9




(F) M3.5*25(4PCS)

10




(A) M6*50(8PCS)

11




(B) M3.5*60(2PCS)
(D) M3.5*40(6PCS)

12




(B) M3.5*60(1PCS)
(D) M3.5*40(3PCS)

13




(B) M3.5*60(6PCS)

14




(D) M3.5*40(16PCS)

15




16




(E) M3.5*30(8PCS)

17



(F) M3.5*25(4PCS)

18



19

