





ASSEMBLY INSTRUCTION




① x20
(Bolt M6x25)




② x2




Ⓐ x1




Ⓑ x1




Ⓒ x1




Ⓓ x1



Ⓔ x1



Ⓕ x1




Ⓖ x1



Ⓗ x4


ASSEMBLY INSTRUCTION



x1




Step 1

50 %




Step 2

100 %




ASSEMBLY INSTRUCTION



x1

Step 1

50 %



Step 2

100 %

