




Assembly Instruction




















Components - Fittings

Please check you have all the panels listed below


Note: The quantities below are the correct amount to complete the assembly. In some cases, more fittings may be supplied than required.

		 Ø5x40mm	 Ø3x12mm		 Ø4x15mm	
A: 69pcs	B: 69pcs	C: 8pcs	D: 10pcs	E: 2pcs	F: 2pcs	
	 Ø4x25mm		 Ø3x16mm	 Ø6x30mm	 Ø4x30mm	
G: 2pcs	H: 8pcs	I: 8pcs	J: 8pcs	K: 31pcs	L: 6pcs	M: 8pcs
 Ø4x14mm					 Ø6x20mm	 Ø4x18mm
N: 48pcs	O: 8pcs	P: 2pcs	Q: 1pc	R: 2pcs	S: 8pcs	T: 11pcs
	 Ø4x25mm					
U: 1pc	V: 2pcs					


Assembly Instruction

						
1: 1pc	2: 1pc	3: 1pc	4: 1pc	5: 1pc	6: 1pc	
						
7: 1pc	8: 1pc	9: 1pc	10: 2pcs	11: 2pcs	12: 4pcs	
						
13: 4pcs	14: 1pc	15: 1pcs	16: 1pc	17: 1pc	18: 1pc	
						
19: 1pc	20: 1pc	21: 1pc	22: 2pcs	23: 2pcs	24: 2pcs	
						
25: 1pc	26: 1pc	27: 1pc	28: 2pcs	29: 3pcs	30: 1pc	31: 1pc
						
32: 1pc	33: 1pc	34: 1pc	35: 1pc	36: 1pc	37: 1pc	38: 1pc




Step 1






Step 2







Step 3



Step 4







Step 5







Step 6

P₂




Step 7



(B)		x5
(K)		x1
(L)	 Ø4x30mm	x6


Step 8



(B)  x8


(K)  x4


Step 9




(B)  x6


Step 10







(A)		x8
(B)		x8
(K)		x4
(M)		x4
(N)		x8








Step 11



(A)		x10
(D)		x2
(M)		x4
(N)		x8
(U)		x1




Step 12




(A)  x4
(C)  x4 Ø5x40mm
(B)  x6
(K)  x6

Step 13




Step 14




(B)  x12

(K)  x4


Step 15



Step 16




Step 17










B		x4
K		x4

Step 18



B		x4
K		x4

Step 19







E  x2

G  x2


H  $\varnothing 4 \times 25 \text{ mm}$ x8

N  $\varnothing 4 \times 14 \text{ mm}$ x32

Step 20



Step 21



I  x8

J  x8
Ø3x16mm

Step 22

