






A x04




B x03




C x02




D x02




E x01




F x01




G x01




H x01




I x01




J x01




K x01




L x01




M x14
M4*12
+1(spare)




N x14
M4*35
+1(spare)



O x06
M6*40
+1(spare)



P x04
M6*45



Q x04
M6




R x01
M10






S x04
M6*50







T x01
M4














N x02
M4*35

Done

