
















# Assembly instruction







# Assembly instruction




|                                                                                                 |                                                                                                  |                                                                                                   |
|-------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------|
| <p>① x2</p>    | <p>② x2</p>     | <p>③ x2</p>    |
| <p>④ x2</p>    | <p>⑤ x2</p>     | <p>⑥ x2</p>    |
| <p>⑦ x14</p>   | <p>⑧ x3</p>     | <p>⑨ x3</p>    |
| <p>⑩ x2</p>   | <p>⑪ x2</p>    | <p>⑫ x2</p>   |
| <p>⑬ x2</p>  | <p>⑭ x1</p>  | <p>⑮ x4</p>  |

# Hardware List


|                                                                                                                                           |                                                                                                                                          |                                                                                                                                                   |
|-------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------|
| <div>A×20 (2+extra)</div> <div></div> <div>M8×60mm</div> | <div>B×17(1+extra)</div> <div></div> <div>M6×50mm</div> | <div>C×2(1+extra)</div> <div></div> <div>M6×40mm</div>         |
| <div>D×8 (1+extra)</div> <div></div> <div>M6×40mm</div>  | <div>E×16(1+extra)</div> <div></div> <div>M6×10mm</div> | <div>F×20 (2+extra)</div> <div></div> <div>Ø18*Ø8.5*1.5T</div> |
| <div>G×2</div> <div></div> <div>M4</div>                 |                                                                                                                                          |                                                                                                                                                   |

1

Step1.



B×2pcs




M6×50mm

C×2pcs



M6×40mm

Step2.




2

E×16pcs



M6×10mm



3

A×2pcs



M8×60mm

B×2pcs




M6×50mm

F×2pcs




Ø18\*Ø8.5\*1.5T




4

B×2pcs




M6×50mm

D×1pc




M6×40mm




5

A×2pcs



M8×60mm

B×2pcs




M6×50mm

F×2pcs



Ø18\*Ø8.5\*1.5T




6

B×2pcs




M6×50mm

D×1pc




M6×40mm



7

A×8pcs




M8×60mm

F×8pcs




Ø18\*Ø8.5\*1.5T

Please pay attention to the position and hole direction on the instruction diagram



8

A×8pcs




M8×60mm

F×8pcs




Ø18\*Ø8.5\*1.5T

Please pay attention to the position and hole direction on the instruction diagram




9




10

D×6pcs




M6×40mm




11


B×3pcs



M6×50mm




12




13

B×4pcs



M6×50mm



Tighten all screws 100%