


EN_ IMPORTANT, RETAIN FOR FUTURE REFERENCE: READ CAREFULLY.






FR_ IMPORTANT: A LIRE ATTENTIVEMENT ET À CONSERVER POUR CONSULTATION ULTÉRIEURE.

ES_ IMPORTANTE, LEA Y GUARDE PARA FUTURAS REFERENCIAS.


DE_ „WICHTIG! SORGFÄLTIG LESEN UND FÜR SPÄTER NACHSCHLAGEN AUFBEWAHREN.“

IT_ IMPORTANTE! CONSERVARE IL PRESENTE MANUALE PER FUTURO RIFERIMENTO E LEGGERLO ATTENTAMENTE.


HARDWARE

 M6x12mm	A x 14 +1 (spare)	 M6x40mm	B x 16 +1 (spare)	 M6x55mm	C x 12 +1 (spare)
	D x 4		E x 8		F x 1

PARTS



01




Note: Do not tighten bolts fully until all parts are connected!

Note: Ne serrez pas les boulons à fond tant que toutes les pièces ne sont pas connectées!


Hinweis: Ziehen Sie die Schrauben erst fest an, wenn alle Teile verbunden sind!

Nota: non serrare completamente i bulloni fino a tutte le parti non sono ancora collegate!

Nota: No apriete los tornillos completamente hasta que todas las partes están conectadas!




C




x 12

F



x 1

02



A




x 6

F



x 1

03




D



x 4

C



100%


80%




100%



04




F




x 1


B




80%



100%


**x2**

B




x 16

F



x 1


**x2**

A




x 8

F



x 1




E



x 8

B




80%



100%



Done



F



x 1