








Parts




① x 1




② x 1




③ x 1




④ x 1




⑤ x 1




⑥ x 1




⑦ x 4




⑧ x 2




⑨ x 1




⑩ x 1



⑪ x 1




⑫ x 1




⑬ x 1



⑭ x 1




⑮ x 1



⑯ x 1




⑰ x 1




⑱ x 1


Parts




19 x 1



20 x 1




21 x 2



22 x 1




23 x 2




24 x 1

Hardware




M8x20mm

Ⓐ x64pcs




M8x35mm

Ⓑ x27pcs




M8x40mm

Ⓒ x4pc




Ⓓ x4pcs




M8x50mm


Ⓕ x1pc




Ⓖ x1pc



Ⓗ x12pcs




Ⓘ x5pcs




Ⓙ x3pcs


step 1




B	X12PCS	A	X4PCS
			
M8X35MM		M8X20MM	

step 2




A	X8PCS
	
M8X20MM	



step 3




C	X2PCS
	
M8X40MM	

step 4




F	X1PC	C	X2PCS
			
M8X50MM		M8X40MM	

step 5




A X10PCS



M8X20MM

step 6




A X20PCS




M8X20MM


step 7




A	X12PCS	B	X1PC
			
M8X20MM		M8X35MM	



step 8




A	X4PCS
	
M8X20MM	


step 9




A	X6PCS	B	X2PCS
			
M8X20MM		M8X35MM	

step 10



B	X8PCS
	
M8X35MM	

step 11



B	X4PCS
M8X35MM	

step 12

