





















INSTALLATION INSTRUCTION




2113--12.13


HARDWARE LIST:

A  M8×20 16PCS	B  M8×30 20PCS	C  M8×55 16PCS	D  M8×80 8PCS
E  M8×100 4PCS	F  Connector Pin 6PCS	G  64PCS	H  M8 40PCS
I  M8 M6 1PC	J  M6×35 10PCS	K  M6 10PCS	L  10PCS
M  2-hole L-brackets 1PC	N  M8 M6 1PC	O  connecting plate 1PC	P  4PCS
Q  4-hole T-bracket 1PC	R  4PCS	S  4-hole square bracket 1PC	T  2PCS


Step 1




Step 2




Step 3




Step 4




Step 5




Step 6





Step 7





Step 8




Step 9




Step 10



Step 11



Step 12



Step 13

