

Website:www.x-cosrack.com E-mail:info@x-cosrack.com
Facebook:www.facebook.com/cosrackofficial


Assembly instructions




Parts included




A * 1pc




B * 1pc




C * 1pc




D * 1pc




E * 1pc




F * 2pcs




G * 1pc




H * 1pc




I * 2pcs




J * 2pcs




① 8+2pcs




② 4+1pcs



③ 12+2pcs




④ 4pcs




⑤ 1pc

Installation steps

Steps 1:Connect A, D, G with screw ①, and then connect B, E, H with screw ①.Attention: Each iron frame is different, please refer to the hole positions shown in the diagram.




Steps 2:Use screw ② to connect wooden board C to the iron frame, use screw ③ to connect mesh I to the iron frame, and use screw ③ to connect iron pipe F to the iron frame. Attention: After inserting all screws into the holes, tighten the screws.



Installation steps

Steps 3:Install adjusting feet ④.



Steps 4:Insert wire J into the hole of board C and complete the installation.

