


DJYC2613HT /DJYC2613B





Exploded View








Fitting



Ax38(+2)
Ø6x35mm



Bx46(+2)
Ø15x10mm



Cx36(+2)
Ø6x30mm



Dx23
Ø4x35mm



Ex88(+2)
Ø3.5x12mm



Fx8
Ø6x40mm



Gx8



Hx8



Ix8



Jx12
Ø3x16mm



Kx7



Lx2


Mx4



CLx3
L330mm


CRx3
L330mm


DLx3
L330mm



DRx3
L330mm


Step 1



x3


Step 2






x3


Step 3








x3

Step 4













x3

Step 5



E
E
E
CL
CL
E
E
E
E
E
E
E
E
4
E
E
E
CR
E
E
E
E
E
E
E
E
E
5
E
E
CR



Ex18


CLx3



CRx3


Step 6



4
A
A
5
A
A


Ax4


Step 7



4
C
B
9



Bx1



Cx1

Step 8



Need Two or More
People To Complete


5
11
B
C
C
B
10



Bx2


Cx2

Step 9



Need Two or More People To Complete







Bx1




Cx1

Step 10







Ax7





Lx2

Step 11












Step 12






Caution : Need to use the correct part #F instead of part #A.







x2

Step 13






Ax1


Bx2



Cx2

Step 14






Ax1



Bx2


Cx2


Step 15










Step 16












Step 17





Step 18







Step 19





Ax4



Ex6



Hx6

x2


Step 20





Bx4


Cx4


Step 21




Need Two or More People To Complete




Cx8




Dx8




Step 22




Need Two or More People To Complete




Bx6



Cx8




Step 23





Ex6

Step 24






Ex24


Gx8



Mx4

Step 25






Step 26




Adjust position as required.







Ix8

Step 27




Step 28



Need Two or More
People To Complete


13
1
15
6
E
E
E
E
E
E
K
K
K



Ex8


Kx2

Step 29




Need Two or More People To Complete





Ex8



Kx2

Step 30

