






ASSEMBLY INSTRUCTION


Office chair







COMPONENT LIST

LABEL	PARTS	DESCRIPTION	QTY
I	M6*20mm 	Bolts	4
J	M6*40mm 	Bolts	2
K	M8*20mm 	Bolts	3
L	M6*16mm 	Bolts	6
M	M8*20mm 	Bolts	3
N	M6*1 	Allen key	1


MM




COMPONENT LIST

LABEL	PARTS	DESCRIPTION	QTY
A		Back	1
B		Headrest	1
C		Seat	1
D		Machine	1
E		Armrest	2
F		Base	1
G		Gaslift	1
H		Casters	5

01





02



03

I *4
M6*20mm



N *1
M6



04

K *3
M8*20mm

N *1
M6



05

J *2





M6*40mm


N *1




M6




06




07



08





**Now, you are an excellent engineer.
No one knows this chair better than you.**