














READ AND SAVE THIS INSTRUCTIONS BEFORE USE

ASSEMBLY & INSTRUCTION MANUAL


MADE IN China
Production date: 03/2026


①  Qty:16+2	②  Qty:16+2	③  Qty:14+1	④  Qty:8+1
⑤  Qty:8+1	⑥  Qty:12+1	⑦  M3x12 Qty:16+2	⑧  CL DL CR DR Qty:2
⑨  Qty:4	⑩  M3x14 Qty:4	 Qty:1	















Make sure the pins are installed correctly as shown with the "check mark" below




Below shows how the pins are used to assemble the panels together.







A x1 	B x1 	C x1 
D x1 	E x1 	F x1 
G x4 	H x1 	I x1 
J x2 	K x2 	L x2 
M x2 	N x2 	

1




8		X 2
7		X 8
1		X 2

2




3		X 2
2		X 2

3




4		X 4
3		X 4

4



5		X 8
4		X 4
3		X 4

5





9




X 4


6




7



1

 X 4

8




3

 X 4

2

 X 4


9



1

X 10

10




2




X 10


11



12




6




X 12


13



14



15



10	  X 4
----	---

16

