











ASSEMBLY INSTRUCTIONS




NO.:CB-1213-KING




spare parts 1

A	Headboard  x1	G	 Slat x39
B	 Footboard x1	H	 Rails plastic slat x26
C	C_L  Side x1 C_R  Side x1	I	 Center plastic slat x26
D	 Bed side bar x2	J	 Bed foot x6
E	 Center Support bar x2	K	K_L  Link Hardware x1 K_R  Link Hardware x1
F	 Metal Leg Support x4		


spare parts 2

a	 5/16*1.5" x 20	g	 1/4 x8
b	 5/16*2.5" x10	h	 5/16 x1
c	 5/16*2" x8	i	 1/4 x1
d	 1/4*1" x8	j	 ⌀5/16" x8
e	 3/4" x32	k	 NUT x1
f	 5/16 x38		


setp:1




setp:2




setp:3




setp:4




setp:5





setp:6




setp:7



spare parts

L	Bedhead ears  x2	M	 Link iron sheet x4
J	 Bed foot x4		
I	 5/16*1" x8	h	 5/16 x1
f	 5/16 x8		

setp: 8



Back of the bed head

