















PARTS LIST



HARDWARE LIST


NO.	Drawing	Description	Qty	PCS SET	NO.	Drawing	Description	Qty	PCS SET
A		∅15x9	27	PCS	F		∅3.5x12	14	PCS
B		∅7x35	27	PCS	G		∅4x35	8	SET
C		∅6x30	8	PCS	H			2	PCS
D		∅3.5x12	26	PCS					
E		12"	2	SET	I			1	PCS
									
									
									

1 ATTENTION

During assembly, first loosely align all screws with the corresponding pre-drilled holes and then tighten the screws one by one.


STEP 1

B x12pcs
D x12pcs
E1 x2pcs
E2 x2pcs



STEP 2


A x2pcs
B x2pcs



STEP 3

A x6pcs


C x3pcs



STEP 4

A x6pcs

C x3pcs




STEP 5

A x5pcs


B x5pcs

C x2pcs




STEP 6

F x14pcs




A	x8pcs
B	x8pcs
D	x8pcs
E3	x2pcs
E4	x2pcs
G	x8pcs



STEP 8

D x6pcs
H x2pcs
I x1pcs



STEP 9

