





1. Determine the direction of the branches.



2.1 Determine the Hole Location
2.2 The Pin Goes Through Crystal Hole
2.3 Bend the excess pins to secure.



The Bending Needles are Uniformly Facing Upwards



3.Twist the tube to the end



X10

X10

X10

X10

X1

X90



X90



X1