


Computer Desk


User Manual



AJ-DJ505937








Warning:Please read this instruction manual carefully before using the product.

version:1.0


Package Contents

Plates and iron components	Assembly tool kit	Instruction manual


Precautions




1. Avoid long-term direct sunlight exposure




2.Stay away from fire




3.keep away from sharp objects




4.Keep infants/children away from assembly parts to avoid choking and suffocation.




5.keep away from corrosive substances



6.Pay attention to avoid cver-tightening fasteners, orthey may induce cra-cking within the board.



7.Prevent objects from being damaged by immersion in water




8.Prevent object collision and damage




9.Be careful to avoid collisions

Installation of Cams and Pins









Screw the pin into the hole. To set the cams correctly, ensure that the arrow on the cam is opening o the hole of the pin it is locking. Lock the cam by tturning the cam head with a screwdriver until it is tightened. Please do not use an electric screwdriver to assemble the unit.












Disassembly Diagram












Parts List

1  X1	2  X1	3  X1
4  X1	5  X1	6  X1
7  X1	8  X1	9  X1



Parts List

10  X1	11  X1	12  X1
13  X1	14  X1	15  X1
16  X1	17  X3	18  X3










Parts List


19  X3	20  X2	21  X2
22  X2	23  X1	24  X1
25  X1	26  X1	27  X1

Parts List

28  X1	29  X1	

Tool sheet


A ST5X40MM  X14+1	B Ø6X30MM  X35+2	C M6X40MM  X86+2	D  X86+2
E  X86+2	F ST3X12MM  X38+2	G ST3.5X14MM  X8	H M4X16MM H1  X3 H2  X6
I  X1	J  X3	CL 14"  X3	CR 14"  X3
DL 14"  X3	DR 14"  X3	#3 	




friendly reminder


To avoid errors and confusion during installation, please remove the screws from the packaging and arrange them neatly beforehand. Please use the correct type and quantity of hardware components by following the steps in the instruction manual.

ASSEMBLY INSTRUCTION






Make sure to use the correct screws to avoid damaging components



✕

Wrong size screw can split the board




√

Correct screw size is correct

Matters needing attention


(1)When installing the screws in the installation step,
the screws do not need to be tightened.
After this installation step is confirmed and the holes are aligned,
then tighten all the screws.

(2)If the screws are tightened during the installation process,
it will cause problems such as misalignment of the screw
holes and misalignment of the board in subsequent installations.



ASSEMBLY INSTRUCTION

Step 1





CR	X3

CL	X3

F	X12
	
ST3x12mm	

Step 2



C	X16
	
M6x40mm	

ASSEMBLY INSTRUCTION


Step 3


E	X2

D	X2

C	X2
M6x40mm	

B	X2
Ø6x30mm	







Step 4

E	X8


D	X8

B	X2
Ø6x30mm	







Step 5



E	X8
D	X8
B	X2
Ø6x30mm	




Step 6



C	X4
M6x40mm	


ASSEMBLY INSTRUCTION

Step 7




C	X16
	
M6x40mm	

Step 8




E	X4
	
D	X4
	
B	X2
	
Ø6x30mm	




ASSEMBLY INSTRUCTION


Step 9



E	X4
D	X4
B	X2
Ø6x30mm	




Step 10




E	X2
D	X2
B	X1
Ø6x30mm	

ASSEMBLY INSTRUCTION


Step 11




E	X6
D	X6
B	X3
Ø6x30mm	



Step 12





C	X4
M6x40mm	



ASSEMBLY INSTRUCTION


Step 13



C	X3
	
M6x40mm	


B	X2
	
Ø6x30mm	


Step 14



E	X3
	


D	X3
	

C	X4
	
M6x40mm	




ASSEMBLY INSTRUCTION

Step 15




E	X4

D	X4




Step 16




E	X4

D	X4




ASSEMBLY INSTRUCTION

Step 17




C	X2
	
M6x40mm	

Step 18




E	X2
D	X2




ASSEMBLY INSTRUCTION

Step 19




E	X4
D	X4




ASSEMBLY INSTRUCTION

Step 20




B	X19
Ø6x30mm	
A	X2
ST5x40mm	

Step 21



J	X1
F	X2
ST3x12mm	
C	X15
M6x40mm	


Step 22




E	X15
D	X15


ASSEMBLY INSTRUCTION

Step 23




C	X8
	
M6x40mm	

Step 24



F	X2
	
ST3x12mm	
E	X8
	
D	X8
	


Step 25



J	X2
I	X1
F	X10
ST3x12mm	

ASSEMBLY INSTRUCTION


Step 26



X2

E	X8
D	X8
C	X8
M6x40mm	

Step 27




X2

H	X2
M4x16mm	
A	X8
ST5x40mm	


ASSEMBLY INSTRUCTION

Step 28



DR	X2
DL	X2
F	X8
ST3x12mm	


Step 29




E	X4
D	X4
C	X4
M6x40mm	

ASSEMBLY INSTRUCTION


Step 30



H	X1
	
M4x16mm	

A	X4
	
ST5x40mm	

Step 31




DR	X1
	

DL	X1
	


F	X4
	
ST3x12mm	

Step 32





ASSEMBLY INSTRUCTION

Step 33



a=b



G	X8
	
ST3.5x14mm	

Thank you
for choosing our product

SEDETA
Made In China