








Parts




① x 1




② x 1




③ x 1




④ x 1




⑤ x 1




⑥ x 1




⑦ x 4




⑧ x 2




⑨ x 1



⑩ x 1




⑪ x 1




⑫ x 1




⑬ x 1



⑭ x 1




⑮ x 1



⑯ x 1




⑰ x 1




⑱ x 1



⑲ x 1




⑳ x 1




㉑ x 1

Hardware




M8x20mm

Ⓐ x60pcs




M8x35mm


Ⓑ x27pcs




Ⓒ x1pc




Ⓓ x4pcs




Ⓗ x12pcs



Ⓘ x5pcs




Ⓙ x2pcs




Ⓚ x1pc


step 1




B	X12PCS	A	X4PCS
			
M8X35MM		M8X20MM	

step 2




A	X8PCS
	
M8X20MM	

step 3




A X8PCS



M8X20MM

step 4




A X20PCS




M8X20MM

step 5




A	X12PCS	B	X1PC
			
M8X20MM		M8X35MM	



step 6




A	X4PCS
	
M8X20MM	


step 7




A	X4PCS	B	X2PCS
			
M8X20MM		M8X35MM	

step 8




B	X8PCS
	
M8X35MM	

step 9



B	X4PCS
---	-------



M8X35MM

step 10

