





A M6*35mm




x18

B M15*10mm



x14

C M6*30mm



x8

D M15*12mm




x4

E M4*30mm




x4

F M5*38mm




x6

G




x2

H




x1

I



x1

J




x1

K




x2

L




x2

M M4*35mm



x2

N M4*12mm




x36

O




x2

P




x4

Q



x2

R




x2

S




x1

T



x1

U



x8

V M3.5*16mm



x8


W

M3.5*14mm






x2

X M8*30mm





x8






STEP 1




A	L	N
		
x12	x2	x2


STEP 2





STEP 3




STEP 4




A	S	W
		
x2	x1	x2

STEP 5




B	C
	
x4	x2


STEP 6




B	C
 x4	 x2

STEP 7




B	D
 x2	 x4
C	X
 x2	 x4


STEP 8



STEP 9





STEP 10





U		x8
V		x8

STEP 11




M		x2
O		x2



STEP 12





STEP 13





STEP 14



STEP 15



STEP 16



STEP 17

