


Assembly Instruction



MADE IN CHINA





Thank you for purchasing our quality product.

Before Beginning & Caution



















- Please take the time to read instructions ,cover to cover.
- Unpack ,inspect and check all bags and components to ensure you have all parts.
- We strongly recommend that you keep children away from the work area to avoid swallowing by mistake due to playing.
- Do not assemble on flooring or carpet, assemble on a clean and non-abrasive surface.
- Save all packing materials until assembly is completed.
- Please dispose of plastic bags safely.
- If you keep the hardware in a bowl or a special area during assembly,you will be less likely to lose them.
- Do not use products unless all screws are tight.


Care & Maintenance

- Dust and pick up spills using a clean ,non-colored ,lint-free cloth.
- Stains may be removed with damp cloth.
- Keep away sharp and chemical stuff from product to avoid serious damaging.




PARTS LIST


1 x1 	2 x1 	3 x1 	4 x1 
5 x1 	6 x1 	7 x1 	8 x1 
9 x1 	10 x1 	11 x1 	12 x2 
13 x2 	14 x2 	15 x2 	16 x1 
17 x1 	18 x1 		



HARDWARE LIST



M4
A×1PC



M5X45mm
B×10PCS




Ø6*30mm
C×20PCS



D1×4PCS




M4*20mm
D2×4PCS




E×4PCS



Ø6.5x36mm
F1×30PCS



Ø15x9.8mm
F2×30PCS



G1×1PC



G2×2PCS



Ø6*M3*16mm
H×7PCS



Ø7*M3.5*12mm
I×53 PCS




14*14*11mm
K×4PCS




L×4PCS

M1(CL)x2PCS

M2(DR)x2PCS



M1(DL)x2PCS




M2(CR)x2PCS



Ø8*M4*30mm
N×8PCS



R1x1PC



R2x1PC



R3x1PC

R



S1x1PC


28x28x18mm



S2x1PC

26x26x13.5mm


S



T×4PCS



For power tools



STEP 1

 C×20PCS

2 x1pc

3 x1pc








4 x1pc

5 x1pc


6 x1pc

7 x1pc







8 x1pc



STEP 2




F1×30PCS




STEP 3


M1-CL




M2-CR



M1-DL



M1-DR



STEP 4



M1(CL)×1PC




I×6PCS

② x1pc



M2(CR)×1PC



③ x1pc





NOTE:


Refer to the images to identify M1-CL (left) and M2-CR (right). Attach M1-CL to #2 panel and M2-CR to #3 panel. [I] screws must go in the exact spots shown.

M1-CL

M2-CR



Make sure the rollers on the slides face downward.



STEP 5




M1(CL)×1PC



M2(CR)×1PC



I×6PCS




5 x1pc




NOTE:

Refer to the images to identify M1-CL (left) and M2-CR (right). Attach M1-CL to #4 panel and M2-CR to #4 panel. [I] screws must go in the exact spots shown.


M1-CL



M2-CR




Make sure the rollers on the slides face downward.



Make sure the rollers on the slides face downward.


STEP 6

 **B**×2PCS


 **A**

5 x1pc


7 x1pc




STEP 7

 **G1**×1PC


 **H**×3PCS



6 x1pc




STEP 8

 **B**×1PCS

 **A**

6×1pc




STEP 9


 **F2**×4PCS



2×1pc





STEP 10

 **B**×3PCS

 **A**


4 x1pc


8 x1pc




STEP 11

 **F2**×2PCS




 **B**×2PCS


 **A**



STEP 2




STEP 1





STEP 12


9 x1pc



STEP 13

-  F2×6PCS
- 
-  B×2PCS
-  A


3 x1pc



STEP 14




L×4PCS



STEP 15




F2×10PCS



STEP 16


 N×8PCS



12 x2pcs


13 x2pcs

14 x2pcs



STEP 17


15 x2pcs




STEP 18



F2×4PCS




10 x1pc




STEP 19




F2×4PCS




11 x1pc



STEP 20



M1(DL)×2PCS






M2(DR)×2PCS

NOTE:

Refer to the images to identify M1-DL (left) and M2-DR (right). Attach M1-DL to #12 panel and M2-DR to #13 panel. [I] screws must go in the exact spots shown.



I×8PCS





STEP 21




D1×2PCS




D2×2PCS



STEP 22




Attention ⚠



STEP 23




T×4PCS




STEP 24

18x1pc




STEP 25


- **I**×12PCS
- **E**×4PCS
- 


16×1pc

17×1pc



STEP 26

- **I**×8PCS
- 
- 17**×1pc



STEP 29



G2×1PC





I×2PCS



D1×1PC



D2×1PC





STEP 30





K×4PCS



H×4PCS



STEP 31

	Ix1PC
	R1x1PC
	R2x1PC
	R3x1PC
	S1x1PC
	S2x1PC
