







Assembly Instructions




HARDWARE LIST

 ① x 2PCS	 ② x 2PCS	 ③ x 8PCS
 ④ x 4PCS	 ⑤ x 1PC	


PARTA LIST

 M6*45mm F x (8+1)PCS	 M6*27mm E x (4+1)PCS	 M6*12mm Q x (6+1)PCS	 M4 S x 1PC
 M12 W x 1PC	 M6 Y x 2PCS	 M6 Z x2PCS	 M6 J x4PCS

STEP 1





STEP 2




③ × 4PCS
E × 4PCS

STEP 3




Note: When connecting the support legs, do not apply excessive force to prevent the screw holes from cracking.

STEP 4





$F \times 4\text{PCS}$

STEP 5



② × 1PC


STEP 6



Note: When connecting the support legs, do not apply excessive force to prevent the screw holes from cracking.


③ × 4PCS

STEP 7





$F \times 4\text{PCS}$

STEP 8



② $\times 1\text{PC}$



STEP 9



Note: When connecting the support legs, do not apply excessive force to prevent the screw holes from cracking.

④ × 4PCS

STEP 10



Z × 2PCS

Y × 2PCS

J × 4PCS

