

Installation method




Marking of holes



Drill holes



Tap expansion plugs into



Place the base and screw it in

precautions

The four corners of the ladder have circular connectors with screw holes for fixing the ladder to the wall. When assembling this ladder, the turning connection only needs to be roughly aligned with the wall. Even if there is looseness, there is no need to worry, because when the ladder is installed on the wall and all four corners are fixed, the ladder will become very stable. It can reduce the difficulty of precise alignment during the assembly process.

