

ASSEMBLY INSTRUCTION



Estimated time for assembly





60:00


What you need

● Use the packaging carton as aworking surface to prevent product damage during assembly.

● Phillips head screwdriver.






































IMPORTANT:














1.Do not tighten bolts / screws completely until all bolts / screws are lined up and inserted into holes.
2.Do not over tighten screws and bolts to avoid stripping
3.Please use hand tools to assemble this product, Do not use power tools.




Packing List

1  x1	2  x1	3  x1	4  x1
5  x1	6  x1	7  x1	8  x1
9  x1	10  x1	11  x1	12  x1
13  x2	14  x1	15  x1	16  x1

17  x3	18  x3	19  x2	20  x1
21  x1	22  x1	23  x2	24  x1
25  x2	26  x2	27  x2	28  x2
29  x1	30  760mm x3		

A1  x3	A2  x3	B1  x3	B2  x3	C M3.5x12  x72
D  x60	E  x60	F M4x12  x10	G M6x30  x12	H M5x40  x2
I  x2	J M3x14  x4	K M7x50  x12	L M6x28  x3	M  x4
N M3.5x40  x14	O  x3	P M4x18  x7	Q  x4	R  x2
S  x4	T  x2	U  x2	V  x1	W M4x40  x2


Step 1



D

x12


Step 2



E

x12


Step 3



D


x8

I




x1

J M3x14



x2


Step 4



E


x8

G M6x30




x4

Step 5




F M4x12




x6

Step 6




I




x1

J M3x14



x2

Step 7




K M7x50




x6

Step 8





D





x8


Step 9






A1	A2	C M3.5x12
 x2	 x2	 x8

Step 10




D
x4

Step 11



A1	A2	C M3.5x12
x1	x1	x4


Step 12



Please note the direction of board 12, the slide rail should be in front.

H M5x40
x2

Step 13




L M6x28



x3

Step 14




E



x4


Step 15



E	G M6x30
x8	x4


Step 16

X2



D
x4

Step 17




E




x4

Step 18





D




x10


Step 19









Step 20






Step 21




G M6x30	K M7x50
x4	x6

Step 22



N M3.5x40
x4

Step 23




N M3.5x40




x2


Step 24



Step 25




D



x6

Step 26





E




x6


Step 27





O	P M4x18
	
x1	x1


Step 28






B1	B2	C M3.5x12
		
x1	x1	x4

Step 29



Step 30


X2



N M3.5x40


x8

Step 31




X2

Step 32





D





x8

Step 33













Step 34












Step 35







B1	B2	C M3.5x12
 x1	 x1	 x4


Step 36






B1	B2	C M3.5x12
 x1	 x1	 x4



Step 37




Step 38



X2

C M3.5x12	Q
	
x8	x4


Step 39



X2

C M3.5x12	P M4x18	R	S
x4	x4	x2	x4


Step 40



X4

C M3.5x12
x16


Step 41





C M3.5x12


x20


Step 42




T	F M4x12
 x2	 x4

Step 43




U
 x2

Step 44



W M4x40



x2

Finish !!!

