


ASSEMBLY INSTRUCTION



Parts List:



Hardware List:





 Ax25	 Bx25	 Cx10	 M4x35mm Dx21	 M3x12mm Ex30	 M4x12mm Fx2
 M4x16mm Gx6	 Hx4	 Ix2	 Jx3	 Kx2	 Lx2
 Mx2	 M6x55mm Nx8	 Ox1			

Diagram 4 illustrates the step of attaching the back panel (4) to the side panel (3). The back panel is shown being aligned with the side panel, and screws (D) and cam bolts (C) are used to secure it.


5




6




7




8




9




10






11



12



13



14

