Assembly Instructions







Component Check List		
A		x4
B		x4
C		x4

Tools Required		
D		Allen Key (Supplied)